This is a CONTROLLED DOCUMENT

EG&G - ROCKY FLATS PLANT ENVIRONMENTAL MANAGEMENT

This is a RED Stamp

ROCKY FLATS PLANT **EMD ADMINISTRATION** PROCEDURES MANUAL Manual No.: Procedure No.: 3-21000-ADM

Page:

Table of Contents, Rev 3

Effective Date:

1 of 4 04/08/92

CATEGORY 1

Organization:

Environmental Management

TABLE OF CONTENTS FOR ENVIRONMENTAL MANAGEMENT DEPARTMENT ADMINISTRATIVE PROCEDURES MANUAL

Procedure No.	Titie	Rev. No.	Effective Date
01.01	ER Organization		
02.01	Indoctrination and Training		
02.02	Personnel Qualifications	0	08/15/91
02.03	Qualification of Audit Personnel		
03.03	Risk Assessment		
03.04	Control of QAA Development	0	09/23/91
04.01	Procurement Document Control	0	04/08/92
05.01	Procedure Development	0	08/02/91
05.02	Development and Control of ARARs		
05.03	RFI/RI Work Plan Development	0	08/15/91
05.04	QAA Development		
05.05	Document Review	0	08/02/91
05.06	QAPM/PCC Procedure Review		
05.07	Preparation of Procedure Change Notices	1	09/23/91
05.08	Forms Control	0	09/23/91
05.11	Preparation of Instructions	0	04/08/92

ADMIN RECORD

A-SW-001040

Manual No.: Procedure No.:

3-21000-ADM Table of Contents, Rev 3

Page:

2 of 4

Effective Date:

04/08/92

CATEGORY 1

Organization:

Environmental Management

Procedure <u>No.</u>	Title	Rev. No.	Effective <u>Date</u>
06.01	Document Control	0	08/02/91
07.01	Control of Purchased Items and Services		
08.01	Control and Identification of Items, Samples, and Data	0	04/08/92
10.01	Inspections	0	04/08/92
12.01	Control of Measuring and Test Equipment	0	04/08/92
13.01	Handling, Shipping and Storage		,
15.01	Control of Nonconforming Items and Activities	0	09/23/91
16.01	Corrective Action	0	04/08/92
17.01	Quality Assurance Records Management	0	02/28/92
18.01	Audits	,	
18.02	Surveillance Activities	1	04/08/92
18.03	Readiness Review	0	08/02/91
20.01	Invoice Management		
AQD.01	Response Plan for Denver Metro Air Pollution Episodes		
AQD.02	Monthly Environmental Monitoring Report		
AQD.04	Radiation Dose Assessment to the Public from Routine Operations		
AQD.05	General Emergency Response		
AQD.06	EIS/ODIS Report		
AQD.08	Preparation of EPA Form R	1	10/10/91

Manual No.: Procedure No.:

3-21000-ADM Table of Contents, Rev 3

Page:

3 of 4

Effective Date:

04/08/92

CATEGORY 1

Organization:

Environmental Management

Procedure No.	Title	Rev. No.	Effective Date
SWD.01	Monthly Discharge Monitoring Reports for NPDES		
SWD.02	Implementation of the Control and Disposition of Incidental Waters		
SWD.20	Monitoring Audits		
NEPA.01	NEPA M&I Design Review		
NEPA.02	NEPA Compliance Committee		
NEPA.03	Completing a Checklist		
NEPA.04	ADM Development		
NEPA.05	ADM Review		
NEPA.06	Preparing Recommendations to DOE, RFO		
NEPA.07	Drafting Categorical Exclusions for DOE, RFO		
NEPA.08	Environmental Assessment Process		
NEPA.09	Preparation of an Environmental Assessment		
NEPA.10	Preparation of a Mitigation Plan		
NEPA.11	NEPA Records Maintenance		
RPD.01	Work Plan/Sampling Plan - When EPA Approval not Required		
RPD.02	Work Plan/Sampling Plan - When EPA Approval Required		
RPD.03	Documents to be Submitted to the Administrative Record		

Manual No.: Procedure No.:

3-21000-ADM Table of Contents, Rev 3

Page:

4 of 4 04/08/92

Effective Date: CATEGORY 1

Organization:

Environmental Management

Procedure <u>No.</u>	Title	Rev. No.	Effective Date
RPD.04	How to Prepare Statements of Work		
RPD.05	Preparing, Processing and Classification of Documents to be Distributed to Outside Agencies		
RPD.06	Preparation of Closure Plans		
RPD.07	Preparation of Technical Evaluations		
RPD.08	How to Establish ARARs		
RPD.10	How to Prepare and Process Milestones		
RPD.11	Tracking Costs and Schedules		
RPD.12	Processing Procurement Documents		
RPD.13	Uniform Requirements for Submission of Plans and Documents by Contractors		
RPD.14	Coordination of Activities with Field Project Management (FPM) and Field Engineering (FE))	
RPD.15	Checklist for the Startup of New Projects		
RPD.16	Standardized Contractor Cost Reporting		
RPD.17	QA Guidelines for Treatability Studies		
RPD.18	QA Guidelines for Health and Safety Treatability Studies		
RPD.19	Cost Guidelines for Submission of Cost Evaluations and Technical Evaluations		
RPD.20	Checklist for Preparing Project Management Plans		

This is a

CONTROLLED DOCUMENT

EG&G - ROCKY FLATS PLANT

ENVIRONMENTAL MANAGEMENT

INSPECTIONS

This is a RED Stamp EG&G ROCKY FLATS PLANT EMD ADMINISTRATIVE PROCEDURES MANUAL

Manual Number: Procedure No. Page: 3-21000-ADM 10.01, Revision O 1 of 7

CATEGORY 1

Effective Date:

May 11, 1992

Organization:

ENVIRONMENTAL MANAGEMENT

Title:

Approved By

INSPECTIONS

prector, Environmental Management

4/8/92

1.0 PURPOSE

The purpose of this procedure is to describe the methods used to perform inspections of Environmental Management Department (EMD) quality-affecting activities. Inspections are to be accomplished as the work is being conducted to ensure that the work is performed to approved documents by qualified personnel and that work documentation is being properly prepared, approved, and controlled.

2.0 SCOPE

The scope of this procedure encompasses the inspection of activities performed in support of EMD activities. This includes inspection of field operations, data management, and other activities designated by the Quality Assurance Program Manager (QAPM) or the responsible manager. This procedure is required when invoked by either the responsible manager for technical inspections or by the QAPM for Quality Assurance (QA) inspections.

3.0 TERMS/DEFINITIONS

- 3.1 Activity Drilling, sampling and/or measurement activity, monitoring, and other activities that result in the production of data. An activity typically is work performed by the contractor or a single subcontractor and is discretely unique; i.e., drilling versus biota sampling. Note: this definition was developed to aid in establishing criteria for the separation of Environmental Management Inspection Reports.
- 3.2 Checklist As used in this procedure is a list of items/activities to be addressed in an inspection.
- 3.3 EM Environmental Management.
- 3.4 EMIR Environmental Management Inspection Report.

REVIEWED FOR CLASSIFICATION/UCH By Lorge H. Lotlork

Manual Number: Procedure No. Page: Effective Date:

3-21000-ADM 10.01, Revision O 2 of 7

Organization:

May 11, 1992

CATEGORY 1

ENVIRONMENTAL MANAGEMENT

- OAA Quality Assurance Addendum to the Quality Assurance Project Plan (QAPjP).
- QAC Quality Assurance Coordinator.
- QA Inspections Inspections performed by the designee of 3.7 the QAPM per the criteria established by the QAPM.
- QAPM Quality Assurance Program Manager. 3.8
- QAPjP Quality Assurance Project Plan.
- 3.10 Technical Inspections Inspections performed by the responsible manager's designee the criteria per established by the responsible manager.

4.0 RESPONSIBILITIES

NOTE

In the interest of implementing total quality management, the responsible Division Manager may elect to participate in the QA Inspection process. If the Division Manager elects to participate in this process, the Division Manager's designee completes the following activities:

- 1. Develop and review applicable checklists,
- 2. Provide inspectors,
- Implement the inspection program, and з.
- Schedule and coordinate the inspection program.

The QAPM will still review, approve, and arrange for issuance of the checklists and will still receive copies of all inspection reports.

- If the Division Managers elect to participate in the implementation of the QA Inspection program for their Division, they are responsible to designate individuals to implement inspections.
- The responsible manager is responsible for supervising 4.2 the inspectors for Technical Inspections and coordinating the scheduling with the QAPM for QA In addition, each responsible manager may Inspections. establish other inspections required to implement their responsibilities (Technical Inspection).

Manual Number: Procedure No. Page: Effective Date: 3-21000-ADM 10.01, Revision O 3 of 7

May 11, 1992

CATEGORY 1

Organization:

ENVIRONMENTAL MANAGEMENT

- 4.3 Inspectors are responsible for performing and documenting field inspections in accordance with this procedure.
- 4.4 The EM QAPM is responsible for approving specific inspection checklists and arranging for QA Inspections, arranging for the issuance of a checklist as a controlled document when needed, maintaining the EMIR log, and reviewing all completed EMIRs for areas of quality concern.

5.0 PROCEDURE

5.1 General

- 5.1.1 The responsible Division Manager may elect to implement the QA Inspection program with concurrence and oversight by the QAPM. This requires notification of the QAPM in writing.
- 5.1.2 Responsible Managers may elect to terminate their implementation of the QA Inspection program (see Step 5.1.1) by notifying the QAPM in writing.
- 5.1.3 The responsible Division Managers shall specify the scope of their implementation program in the written notification described in Steps 5.1.1 or 5.1.2.
- 5.1.4 The QAPM shall establish and approve a set of QA Inspection Checklists establishing minimum inspection checklist content requirements.
- Approved QA Checklists shall be placed under controlled distribution in accordance with 3-21000-ADM-06.01, Document Control. Other inspection checklists may be placed under controlled distribution at the discretion of the responsible manager.
- 5.1.6 The QAPM (for QA Inspections) or responsible manager's designee (for Technical Inspections) shall coordinate with work managers to identify those activities that are in progress.

EG&G ROCKY FLATS PLANT EMD ADMINISTRATIVE PROCEDURES MANUAL CATEGORY 1	Manual Number: 3-21000-ADM Procedure No. 10.01, Revision O Page: 4 of 7 Effective Date: May 11, 1992 Organization: ENVIRONMENTAL MANAGEMENT
5.1.7	The QAPM or responsible manager's designee (as applicable) shall specify activities requiring inspection.
5.1.8	QA Inspections shall be conducted on a frequency approved by the QAPM. The responsible managers shall establish the schedule for Technical Inspections of EM activities in their area of responsibility. The frequency of Technical Inspections shall be based on past history, risk, complexity, importance, and applicable regulatory requirements.
5.1.9	Technical Inspections shall be documented. This documentation is typically recorded on the EM Inspection Report forms (Attachment 1).
5.1.10	The QAPM or designee shall assign unique identifiers for each scheduled inspection.
5.1.11	Checklists shall be prepared for work procedures requiring inspections.
5.1.12	Checklists shall be approved by the QAPM for QA Inspections or by the responsible manager for Technical Inspections.
5.1.13	Completed checklists shall be attached to the EMIR and become part of the record of inspection.
5.2 Inspection	n

5.2 Inspection

- 5.2.1 The inspector shall assemble and/or prepare a checklist based on consideration of the following documents:
 - the EM QAPjP (if applicable);
 - the applicable activity-specific QAA; activity-specific work plan, and the work procedures;
 - Environmental Management Inspection Checklist Manual; and
 - other applicable documents.

The inspector's checklist shall include all applicable items from the Environmental

Manual Number:
Procedure No.
Page:
Effective Date:

3-21000-ADM 10.01, Revision 0 5 of 7 May 11, 1992

CATEGORY 1

Organization:

ENVIRONMENTAL MANAGEMENT

Management Inspection Checklist Manual. Additional checklist items may be added by the inspector at this time without approvals.

- 5.2.2 The inspector shall conduct the inspection by:
 - 5.2.2.1 Verifying that current approved work plans, work procedures, other technical documents are in use.
 - 5.2.2.2 Verifying that current approved and applicable training has been completed.
 - 5.2.2.3 Inspecting the items/activities addressed in the checklists.
 - 5.2.2.4 Documenting the inspection results by:
 - Initialing the inspected items on the checklist(s);
 - Addressing all items of deviations and deficiency on the checklist(s).
 - Authenticating the checklist(s);
 - 5.2.2.5 Notifying the designated individual of observed problem areas within 2 working days. (For QA Inspection the designated individual is the QAPM or designee. For Technical Inspection the designated individual is the responsible manager or designee.)
 - 5.2.2.6 Identifying potential needs for Document Change Notices (DCNs) (see 3-21000-ADM-05.07, Preparation of Document Change Notices) and Nonconformance Reports (NCRs) (see 3-21000-ADM-15.01, Control of Nonconforming Items and Activities);

INSPECTIONS

EG&G ROCKY FLATS PLANT EMD ADMINISTRATIVE PROCEDURES MANUAL Manual Number:
Procedure No.
Page:
Effective Date:

3-21000-ADM 10.01, Revision O 6 of 7 May 11, 1992

CATEGORY 1

Organization:

ENVIRONMENTAL MANAGEMENT

and for initiating these documents when appropriate.

- 5.2.3 The inspector records the unique identifier for this inspection on the EMIR.
- 5.2.4 The inspector shall submit a copy of the completed EMIR, with completed checklists, to the EM QAPM for QA Inspections and to the responsible manager for all inspections.
- 5.2.5 The inspector shall transmit the completed EMIR in accordance with 5-21000-FOP.02, Transmittal of Field OA Records.

6.0 REFERENCES

- 1. Environmental Management Quality Assurance Program Description (21000-QAPD)
- 2. Environmental Management Quality Assurance Project Plan (21000-QAPjP)
- 3. Environmental Management Inspection Checklist Manual
- 4. Environmental Management Administrative Procedure No. 3-21000-ADM 05.07, Preparation of Document Change Notices
- 5. Environmental Management Administrative Procedure No. 3-21000-ADM 06.01, Document Control
- 6. Environmental Management Administrative Procedure No. 3-21000-ADM 15.01, Control of Nonconforming Items and Activities
- 7. Environmental Management Operations Procedure No. 5-21000-FOP.02, Transmittal of Field QA Records

7.0 ATTACHMENTS

Attachment 1 - EM Inspection Report Form, Part I

Manual Number: Procedure No. Page: 3-21000-ADM 10.01, Revision O 7 of 7

May 11, 1992

CATEGORY 1

Effective Date: Organization:

ENVIRONMENTAL MANAGEMENT

Attachment 1
EM Inspection Report (EMIR)
Part I

·	
Mas	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
- Alloh	
OHHIM.	
The state of the s	
_ 	
Signature	Date
	Signature - Project Manager, RPD QC, EMA